

17. APPENDIX D: L CHANNEL DETAILS



Figure 5 L Channel Details

Notice deformation on L Channel sections. The Cover plates has sheared away from the L Channel and the L Channel itself is plastically deformed due to the bending moment experienced in the stanchions when the roof cover plates pressed against it.

CONTROLLED DISCLOSURE

When downloaded from the EDMS, this document is uncontrolled and the responsibility rests with the user to ensure it is in line with the authorised version on the system.