

	PROCUREMENT REQUEST	Template Identifier	240-76879530	Rev	2
		Document Identifier	N/A	Rev	N/A
		Effective Date	01 February 2014		
		Review Date	July 2020		

TECHNICAL/FUNCTIONAL EVALUATION CRITERIA:

Standby Emergency Weld Repair Service For Unit 1 & 2

- No points will be awarded for any requirements **not** met
- Valid ISO 3834 Certificates must be returned with tender doc, otherwise tender will not be considered.
- The overall minimum threshold is **81%**.
- Eskom reserves the right to lower the minimum threshold if they so wish and only if no tenderers met the threshold of 81 %.
- A minimum 2 calendar days' notice will be given to mobilize and establish site.

Evaluation Criteria	Weighting
Technical tender returnable documents evaluations	
1) Lead time to site establish after order is placed i. > 5 Calendar days = 0% (will not be considered) ii. 3 - 5 calendar days = 10% iii. <3 calendar days = 20%	20
2) Method statement and QCP i. Method statement not provided = 0% (will not be considered) ii. Method statement provided, but with no QCP = 15% iii. Method statement provided, with QCP addressing intervention points = 30%	30
3) Welding certificates applicable to the code i. Valid ISO 3834 Certificates provided = 20% (if not provided tender will not be considered) ii. Applicable WPS, WPQR, WQR and QCP provided = 10%	30
4) Proof provided of similar work done in confined space with reference contact detail i. Similar work done <3 times = 0% (will not be considered) ii. Similar work done 3 times = 10% iii. Similar work done 5 times = 20%	20

Controlled Disclosure

When downloaded from the document management system, this document is uncontrolled and the responsibility rests with the user to ensure it is in line with the authorised version on the system.

No part of this document may be reproduced without the expressed consent of the copyright holder, Eskom Holdings SOC Ltd, Reg No 2002/015527/30.