

PROJECT BRAVO

GOODMAN JACK TEST RESULTS

SUMMARY OF TESTS CONDUCTED

Sec A - BH 11 N	11 tests. 5 successful. Borehole appeared to be drilled Nx casing dia to 16.5m
Sec B - BH 12 N	17 tests. 4 successful.. Borehole dia larger then 80mm from 12.5m and up.
Sec C - BH 13 N	11 tests. 10 successful.
Sec D - BH 28	12 tests. . 10 successful.
Sec E - BH 29	12 tests. 8 successful. BH dia larger then 80mm from 14.5m and up.
Sec F - BH 32	13 tests. 7 successful.
Sec G - BH 36	17 tests. 9 successful
Sec H - BH 38	14 tests. 11 successful.
Sec J - BH 38 N	14 tests. 9 successful.
Sec L - BH 41 N	11 tests. 6 successful.
Sec M - BH 58	16 tests. 9 successful.

Sec O - Electronic copy

164 attempted test positions with 88 successful tests.

Failure caused mainly by oversized boreholes and then by abrupt variation in the borehole diameters.