


Factor of Safety: 1.03



CLIENT: Eskom

PROJECT: Bravo

FIGURE 4: Stability analysis -15m cut in tillite

COMPILED BY: HJS

DRAWN BY: HJS

CHECKED BY: HJS

Date: October 2007

Scale : n/a

Drawing No.

Partridge, Maud and Associates

Consultants in the Earth Sciences

PO Box 1050
Parklands
2121
Tel: (011) 646 3324
email: tcp@lafrica.com