


Factor of Safety: 1.89



CLIENT: Eskom		
PROJECT: Bravo		
FIGURE 5: Stability analysis -15m cut in tillite - drained		
COMPILED BY: HJS	Date: October 2007	Drawing No.
DRAWN BY: HJS	Scale : n/a	
CHECKED BY: HJS		
Partridge, Maud and Associates		PO Box 1050 Portlands 2121 Tel: (011) 646 3324 email: hcp@kafica.com
Consultants in the Earth Sciences		