


# Factor of Safety: 1.02



CLIENT: Eskom

PROJECT: Bravo

FIGURE 6a: Stability analysis -fill overlying diabase

COMPILED BY: HJS

DRAWN BY: HJS

CHECKED BY: HJS

Date: October 2007

Scale : n/a

Drawing No.

Partridge, Maud and Associates

Consultants in the Earth Sciences

PO Box 1050  
Portlands  
2121  
Tel: (011) 646 3324  
email: hcp@partridge.com