


Factor of Safety: 1.53



CLIENT: Eskom		
PROJECT: Bravo		
FIGURE 6b: Stability analysis -fill overlying diabase		
COMPILED BY: HJS	Date: October 2007	Drawing No.
DRAWN BY: HJS	Scale : n/a	
CHECKED BY: HJS		
Partridge, Maud and Associates		
Consultants in the Earth Sciences		

PO Box 1050
Portlands
2121
Tel: (011) 646 3324
email: hcp@kafica.com