


Factor of Safety: 1.44



CLIENT: Eskom		
PROJECT: Bravo		
FIGURE 7: Stability analysis -fill overlying diabase		
COMPILED BY: HJS	Date: October 2007	Drawing No.
DRAWN BY: HJS		
CHECKED BY: HJS	Scale : n/a	
Partridge, Maud and Associates		PO Box 1050 Parklands 2121 Tel: (011) 646 3324 email: hcp@jafica.com
Consultants in the Earth Sciences		